

OCI Viewers

Instructions on how to use the various OCI viewers

- [DDC Raw](#)

DDC Raw

The DDC Raw Viewer is used to display the DDC Raw captures. The DDC Raw captures are used for examining the raw samples out of the ADC. This mode is used for various tests:

- Line Tune Dark
- ADC Sample Point sweep
- RG Mag sweep
- RG Low sweep

Image not found or type unknown

